



Ministry of Health and Long-Term Care

Ministère de la Santé et des Soins de longue durée

Inspection Report under the Long-Term Care Homes Act, 2007

Rapport d'inspection sous la Loi de 2007 sur les foyers de soins de longue durée

**Health System Accountability and Performance Division
Performance Improvement and Compliance Branch**

**Division de la responsabilisation et de la performance du système de santé
Direction de l'amélioration de la performance et de la conformité**

Hamilton Service Area Office
119 King Street West, 11th Floor
HAMILTON, ON, L8P-4Y7
Telephone: (905) 546-8294
Facsimile: (905) 546-8255

Bureau régional de services de Hamilton
119, rue King Ouest, 11ième étage
HAMILTON, ON, L8P-4Y7
Téléphone: (905) 546-8294
Télécopieur: (905) 546-8255

Public Copy/Copie du public

Report Date(s) / Date(s) du Rapport	Inspection No / No de l'inspection	Log # / Registre no	Type of Inspection / Genre d'inspection
Jun 19, 2014	2014_189120_0040	H-000774-14	Other

Licensee/Titulaire de permis

VIGOUR LIMITED PARTNERSHIP ON BEHALF OF VIGOUR
302 Town Centre Blvd, Suite #200, MARKHAM, ON, L3R-0E8

Long-Term Care Home/Foyer de soins de longue durée

LEISUREWORLD CAREGIVING CENTRE - STREETSVILLE
1742 BRISTOL ROAD WEST, MISSISSAUGA, ON, L5M-1X9

Name of Inspector(s)/Nom de l'inspecteur ou des inspecteurs

BERNADETTE SUSNIK (120)

Inspection Summary/Résumé de l'inspection

The purpose of this inspection was to conduct an Other inspection.

This inspection was conducted on the following date(s): June 13, 2014

During the course of the inspection, the inspector(s) spoke with the Administrator

During the course of the inspection, the inspector(s) toured the home and measured illumination levels in 2 random resident bedrooms, 2 washrooms, one corridor, one tub room, 2 lounge rooms and the dining room.

**The following Inspection Protocols were used during this inspection:
Safe and Secure Home**



Findings of Non-Compliance were found during this inspection.

NON-COMPLIANCE / NON - RESPECT DES EXIGENCES	
Legend	Legendé
WN – Written Notification VPC – Voluntary Plan of Correction DR – Director Referral CO – Compliance Order WAO – Work and Activity Order	WN – Avis écrit VPC – Plan de redressement volontaire DR – Aiguillage au directeur CO – Ordre de conformité WAO – Ordres : travaux et activités
Non-compliance with requirements under the Long-Term Care Homes Act, 2007 (LTCHA) was found. (A requirement under the LTCHA includes the requirements contained in the items listed in the definition of "requirement under this Act" in subsection 2(1) of the LTCHA.)	Le non-respect des exigences de la Loi de 2007 sur les foyers de soins de longue durée (LFSLD) a été constaté. (Une exigence de la loi comprend les exigences qui font partie des éléments énumérés dans la définition de « exigence prévue par la présente loi », au paragraphe 2(1) de la LFSLD.
The following constitutes written notification of non-compliance under paragraph 1 of section 152 of the LTCHA.	Ce qui suit constitue un avis écrit de non-respect aux termes du paragraphe 1 de l'article 152 de la LFSLD.



WN #1: The Licensee has failed to comply with O.Reg 79/10, s. 18. Every licensee of a long-term care home shall ensure that the lighting requirements set out in the Table to this section are maintained. O. Reg. 79/10, s. 18.

TABLE

Homes to which the 2009 design manual applies

Location - Lux

Enclosed Stairways - Minimum levels of 322.92 lux continuous consistent lighting throughout

All corridors - Minimum levels of 322.92 lux continuous consistent lighting throughout

In all other areas of the home, including resident bedrooms and vestibules, washrooms, and tub and shower rooms. - Minimum levels of 322.92 lux

All other homes

Location - Lux

Stairways - Minimum levels of 322.92 lux continuous consistent lighting throughout

All corridors - Minimum levels of 215.28 lux continuous consistent lighting throughout

In all other areas of the home - Minimum levels of 215.28 lux

Each drug cabinet - Minimum levels of 1,076.39 lux

At the bed of each resident when the bed is at the reading position - Minimum levels of 376.73 lux

O. Reg. 79/10, s. 18, Table; O. Reg. 363/11, s. 4

Findings/Faits saillants :

1. The licensee did not ensure that the lighting requirements as set out in the lighting table were maintained.

Using a hand held Sekonic Handi Lumi analog illumination meter, illumination levels were measured in various areas of the home. Non-compliance with levels were specifically identified in resident rooms, resident washrooms, the main foyer lounge and the dining room.

*A private room and washroom were evaluated by closing the window curtains and turning on all available lights. The only room light available was a wall mounted fluorescent light over the head of the bed. When centrally positioned in the bedroom, with the meter held 36 inches above the floor and facing the over bed light source, the lux level was 0. The lux was 390 centrally over the bed area and dropped as the meter



was moved to the foot of the bed and to the center of the room. The fluorescent over bed light was measured and was 675 lux, well above the required standard of 376.73 lux. General room illumination levels did not achieve a minimum of 215.28 lux in and around the entrance to the room (general path of travel) or in and around the entire bed or any task area where activities take place such as dressing, nail care, bed making, crafts or transfers to and from the bed and lift equipment.

*The washroom located in the above private room was equipped with a wall mounted lighting fixture above the sink. The level of illumination over the sink was 110 lux and zero lux over the toilet. The required minimum illumination level is 215.28 lux over both task areas, such as the toilet and the sink.

*A semi-private room and washroom were evaluated by closing the window curtains and turning on all available lights. The only room lights available were two wall mounted fluorescent lights, one over the head of each bed. When centrally positioned in the bedroom, with the meter held 36 inches above the floor and facing the over bed light sources, the lux level was 30. The lux was 200 centrally over each bed area and dropped as the meter was moved to the foot of the bed and to the center of the room. The fluorescent over bed light was measured and was 600 lux, well above the required standard of 376.73 lux. General room illumination levels did not achieve a minimum of 215.28 lux in and around the entrance to the room (general path of travel) or in and around the entire bed or any task area where activities take place such as dressing, nail care, bed making, transfers to and from the bed and lift equipment.

*The washroom located in the above semi-private room was equipped with a wall mounted lighting fixture above the sink. The level of illumination was 150 lux over both the sink and the toilet. The required minimum illumination level is 215.28 lux over both task areas.

*The dining room was measured, however daylight could not be excluded from the room and the measurements were taken from fixtures located towards a wall farthest from the windows. The room was equipped with over 25 ceiling mounted dome lights, some with 2 bulbs and some with one. A lux of 65 was achieved when the meter was positioned directly under a light fixture (at table height) and the fixture was also centrally located over a table. Some light fixtures that emitted a white light were between 85-90 lux. The minimum required level of 215.28 lux was not achieved.

*The main foyer lounge space was not measured, but was observed to be equipped



**Ministry of Health and
Long-Term Care**

**Ministère de la Santé et des
Soins de longue durée**

**Inspection Report under
the Long-Term Care
Homes Act, 2007**

**Rapport d'inspection sous la
Loi de 2007 sur les foyers de
soins de longue durée**

with similar ceiling mounted dome lights as the dining room. The area appeared to be dark despite the lighting provided.

The licensee had not taken any steps to evaluate the illumination levels in the home and a discussion was held with the administrator to have the levels independently evaluated to determine compliance with the lighting table identified above. [s. 18]

Additional Required Actions:

VPC - pursuant to the Long-Term Care Homes Act, 2007, S.O. 2007, c.8, s.152(2) the licensee is hereby requested to prepare a written plan of correction for achieving compliance to ensure that lighting requirements set out in the Table to this section are maintained, to be implemented voluntarily.

Issued on this 19th day of June, 2014

Signature of Inspector(s)/Signature de l'inspecteur ou des inspecteurs