

Inspection Report under the Long-Term Care Homes Act, 2007

Rapport d'inspection prevue le *Loi de 2007 les foyers de soins de longue durée*

Ministry of Health and Long-Term Care

Health System Accountability and Performance Division Performance Improvement and Compliance Branch

Ministère de la Santé et des Soins de longue durée

Division de la responsabilisation et de la performance du système de santé Direction de l'amélioration de la performance et de la conformité Hamilton Service Area Office 119 King Street West, 11th Floor Hamilton, ON L8P 4Y7

Telephone: 905-546-8294 Facsimilie: 905-546-8255 Bureau régional de services de Hamilton 119, rue King Quest, 11iém étage Hamilton, ON L8P 4Y7

Téléphone: 905-546-8294 Télécopieur: 905-546-8255

	Licensee Copy/Copie du Titula	aire Public Copy/Copie Public	
Date of inspection/Date de l'inspection	Inspection No/ d'inspection	Type of Inspection/Genre d'inspection	
02 and 17 November 2010	2010_127_2844_02Nov095629	Critical Incident (H-02100)	
Licensee/Titulaire			
Revera Long Term Care Inc., 55 Standish Court, 8 th Floor, Mississauga ON L5R 4B2			
Long-Term Care Home/Foyer de soins de longue durée			
The Meadows Long Term Care Centre, 12 Tranquility Avenue, Ancaster ON L9G 5C2			
Name of Inspector(s)/Nom de l'inspecteur(s)			
Richard Hayden, Long Term Care Homes Inspector – Environmental Health #127			
Inspection Summary / Sommaire d'inspection			
The purpose of this inspection was to conduct a critical incident inspection.			
During the course of the inspection, the inspector spoke with the administrator, director of care and the environmental services manager. During the course of the inspection, the inspector undertook a visual inspection of mechanical lifts in the home,			
reviewed and took copies of portions of the resident's file/plan of care, the home's incident report and preventive maintenance/safety audit reports for mechanical lifts.			
The following Inspection Protocols were used during this inspection: • Accommodation Services - Maintenance			
Findings of Non-Compliance were found during this inspection. The following action was taken:			
1 WN			



Ministry of Health and Long-Term Care

Ministère de la Santé et des Soins de longue durée

Inspection Report under the Long-Term Care Homes Act, 2007 Rapport d'inspection prevue le Loi de 2007 les foyers de soins de longue durée

NON-COMPLIANCE / Non-respectés

Definitions/Définitions

WN - Written Notifications/Avis écrit

VPC - Voluntary Plan of Correction/Plan de redressement volontaire

DR – Director Referral/Régisseur envoyeCO – Compliance Order/Ordres de conformité

WAO - Work and Activity Order/Ordres: travaux et activitiés

The following constitutes written notification of non-compliance under paragraph 1 of section 152 of the LTCHA.

Non-compliance with requirements under the Long-Term Care Homes Act, 2007 (LTCHA) was found. (A requirement under the LTCHA includes the requirements contained in the items listed in the definition of "requirement under this Act" in subsection 2(1) of the LTCHA.)

Le sulvant constituer un avis d'ecrit de l'exigences prevue le paragraph 1 de section 152 de les foyers de soins de longue dureé.

Non-respect avec les exigences sur le Loi de 2007 les foyers de soins de longue dureé à trouvé. (Une exigence dans le loi comprend les exigences contenues dans les points énumérés dans la définition de "exigence prevue par la présente loi" au paragraphe 2(1) de la loi.

WN #1: The Licensee has failed to comply with O. Reg. 79/10, s. 90(2)(a):

- 90. (2) The licensee shall ensure that procedures are developed and implemented to ensure that,
 - (a) electrical and non-electrical equipment, including mechanical lifts, are kept in good repair, and maintained and cleaned at a level that meets manufacturer specifications, at a minimum;

Findings:

02 November 2010

An identified resident was being transferred from bed to wheelchair in October 2010 via a mechanical lift with 2 staff members present. The sling came undone and the resident slid out. The resident received injuries as a result. The sling and lift were tagged out of service immediately following the incident. An inspection of other slings in the home revealed that two others had a similar fault with the clips as did the one involved in the incident. Those slings were also removed from service at that time.

17 November 2010 - Lifts are inspected and load-tested annually by ARJO-Huntleigh. The last inspection by ARJO-Huntleigh for all lifts was February 2010. Otherwise, lifts are inspected by the staff on every shift before use.

It is not possible to determine if the clip on the sling used for the identified resident was defective before the lift or if it became defective during the lift of October 2010. However, two other slings with an identical defect were discovered on the same day.

	or Representative of Licensee lu représentant désigné	Signature of Health System Accountability and Performance Division representative/Signature du (de la) représentant(e) de la Division de la responsabilisation et de la performance du système de santé.
Title:	Date:	Date of Report (if different from date(s) of inspection).
		16 December 2010