



**Inspection Report  
under the *Long-Term  
Care Homes Act, 2007***

**Rapport d'inspection  
prévues le *Loi de 2007  
les foyers de soins de  
longue durée***

**Ministry of Health and Long-Term Care**

Health System Accountability and Performance Division  
Performance Improvement and Compliance Branch

Ottawa Service Area Office  
347 Preston St., 4<sup>th</sup> Floor  
Ottawa ON K1S 3J4

Bureau régional de services d'Ottawa  
347, rue Preston, 4<sup>ième</sup> étage  
Ottawa ON K1S 3J4

**Ministère de la Santé et des Soins de  
longue durée**

Division de la responsabilisation et de la performance du  
système de santé  
Direction de l'amélioration de la performance et de la  
conformité

Telephone: 613-569-5602  
Facsimile: 613-569-9670

Téléphone: 613-569-5602  
Télécopieur: 613-569-9670

Licensee Copy/Copie du Titulaire	<input checked="" type="checkbox"/> Public Copy/Copie Public
----------------------------------	--

<b>Date(s) of inspection/Date de l'inspection</b> November 24, 2010	<b>Inspection No/ d'inspection</b> 2010_102_2843_24Nov131002	<b>Type of Inspection/Genre d'inspection</b> Critical Incident Log # O-002143
<b>Licensee/Titulaire</b> Yee Hong Cente For Geriatric Care 2311 McNicoll Avenue Scarborough, Ontario M1V 5L3 Fax # 416 321 6313		
<b>Long-Term Care Home/Foyer de soins de longue durée</b> Yee Hong Centre-Scarborough Finch 60 Scottfield Drive Scarborough, Ontario M1S 5T7 Fax# 416 321 0034		
<b>Name of Inspector(s)/Nom de l'inspecteur(s)</b> Wendy Berry (102)		

**Inspection Summary/Sommaire d'inspection**

The purpose of this inspection was to conduct a critical incident inspection related to a mechanical lift and injury to a resident.

During the course of the inspection, the inspector spoke with 3 Assistant Directors of Resident Care (ADRCs), and 1 Registered Practical Nurse (RPN).

During the course of the inspection, the inspector observed the 6<sup>th</sup> floor north wing tub room bath tub and mechanical lift; observed a resident's room that is equipped with a ceiling lift; reviewed operating instructions posted for the 6<sup>th</sup> floor north bath tub lift; reviewed the 6<sup>th</sup> floor binder documents titled "Daily inspection of floor lifts" for October 2010 and a document titled "Operating and Care Instructions" for the Allenti tub lift located in a binder labeled "Equipment Operating Instructions"; observed a resident who was the subject of the Critical Incident.

The following Inspection Protocols were used during this inspection: Safe and Secure Home and Accommodation Services-maintenance.

1 Finding of Non-Compliance were found during this inspection. The following action was taken:

1 WN



**NON- COMPLIANCE / (Non-respectés)**

**Definitions/Définitions**

WN – Written Notifications/Avis écrit  
VPC – Voluntary Plan of Correction/Plan de redressement volontaire  
DR – Director Referral/Régisseur envoyé  
CO – Compliance Order/Ordres de conformité  
WAO – Work and Activity Order/Ordres: travaux et activités

The following constitutes written notification of non-compliance under paragraph 1 of section 152 of the LTCHA.

Non-compliance with requirements under the *Long-Term Care Homes Act, 2007* (LTCHA) was found. (A requirement under the LTCHA includes the requirements contained in the items listed in the definition of "requirement under this Act" in subsection 2(1) of the LTCHA.)

Le suivant constituer un avis d'écrit de l'exigence prévue le paragraphe 1 de section 152 de les foyers de soins de longue durée.

Non-respect avec les exigences sur le *Loi de 2007 les foyers de soins de longue durée* à trouvé. (Une exigence dans le loi comprend les exigences contenues dans les points énumérés dans la définition de "exigence prévue par la présente loi" au paragraphe 2(1) de la loi.

**WN #1:** The Licensee has failed to comply with O. Reg. 79/10, s. 23. Every licensee of a long-term care home shall ensure that staff use all equipment, supplies, devices, assistive aids and positioning aids in the home in accordance with manufacturers' instructions.

**Findings: 1.** Staff are not following manufacturers' instructions that are identified in the "Operating and Care Instructions" manual provided for the ARJO Allenti bathtub lift:

- On October 02, 2010, 2 Personal Support Workers (PSWs) used the Allenti bath lift for the transfer of a resident from her bed. During this transfer, the identified resident sustained a head injury. The progress notes state "1 PSW described that resident's head bumped to the bath tub seat rail while transferring resident from bed to seat for a shower".
- The "Operating and Care Instructions" for the Allenti lift state "The resident needs to be able to sit in an upright position, normally defined as active or semi active." Resident involved is described in the "Care Plan 2010 " plan of care notes as "total dependence"; "Bathing: requires total assistance"; "Mobility: requires total assistance"; "Toilet Use: no trunk control".

Inspector ID #: 102

Signature of Licensee or Representative of Licensee  
Signature du Titulaire du représentant désigné

Signature of Health System Accountability and Performance Division  
representative/Signature du (de la) représentant(e) de la Division de la  
responsabilisation et de la performance du système de santé.

Title: Date:

Date of Report: (if different from date(s) of inspection).

December 17, 2010