

Inspection Report Under the Fixing Long-Term Care Act, 2021

Ministry of Long-Term Care

Long-Term Care Operations Division Long-Term Care Inspections Branch

London District

130 Dufferin Avenue, 4th Floor London, ON, N6A 5R2 Telephone: (800) 663-3775

	Original Public Report
Report Issue Date: August 17, 2023	
Inspection Number: 2023-1259-0006	
Inspection Type:	
District Initiated	
Licensee: Maplewood Nursing Home Limited	
Long Term Care Home and City: Cedarwood Village, Simcoe	
Lead Inspector	Inspector Digital Signature
Peter Hannaberg (721821)	

INSPECTION SUMMARY

The inspection occurred onsite on the following date(s): August 14, 2023.

The following intake(s) were inspected:

• Intake #00094189 was a District-Initiated inspection regarding air conditioning and temperatures in the home.

The following **Inspection Protocols** were used during this inspection:

Safe and Secure Home
Infection Prevention and Control



Inspection Report Under the Fixing Long-Term Care Act, 2021

Ministry of Long-Term Care

Long-Term Care Operations Division Long-Term Care Inspections Branch

London District

130 Dufferin Avenue, 4th Floor London, ON, N6A 5R2 Telephone: (800) 663-3775

INSPECTION RESULTS

WRITTEN NOTIFICATION: Air temperature

NC #001 Written Notification pursuant to FLTCA, 2021, s. 154 (1) 1.

Non-compliance with: O. Reg. 246/22, s. 24 (3)

The licensee has failed to document the temperature required to be measured under subsection (2) at least once every morning, once every afternoon between twelve and five p.m., and once every evening or night.

Per O. Reg 246/22 subsection (2), the licensee is required to measure and document the air temperature in at least two resident bedrooms in different parts of the home, and one resident common area on every floor of the home.

Rationale and Summary

Based on review of the home's air temperature monitoring records from August 1 to 13, 2023, temperatures were not documented in the resident bedrooms six times in the morning, three times in the afternoon, and three times at night. In the same time frame, temperatures were not documented in resident common areas three times during the morning, one time in the afternoon, and one time at night.

There was a risk to residents that the heat-related illness plan would not be implemented as required when the temperatures were not measured.

Sources: Air temperature monitoring records for August 2023.

[721821]