



Ministry of Health and
Long-Term Care

Ministère de la Santé et des
Soins de longue durée

Inspection Report under
the Long-Term Care
Homes Act, 2007

Rapport d'inspection sous la
Loi de 2007 sur les foyers de
soins de longue durée

Health System Accountability and
Performance Division
Performance Improvement and
Compliance Branch

Division de la responsabilisation et de la
performance du système de santé
Direction de l'amélioration de la
performance et de la conformité

Hamilton Service Area Office
119 King Street West, 11th Floor
HAMILTON, ON, L8P-4Y7
Telephone: (905) 546-8294
Facsimile: (905) 546-8255

Bureau régional de services de
Hamilton
119, rue King Ouest, 11^{ième} étage
HAMILTON, ON, L8P-4Y7
Téléphone: (905) 546-8294
Télécopieur: (905) 546-8255

Public Copy/Copie du public

Report Date(s) / Date(s) du Rapport	Inspection No / No de l'inspection	Log # / Registre no	Type of Inspection / Genre d'inspection
Oct 7, 2013	2013_189120_0068	H-000499- 13	Other

Licensee/Titulaire de permis

THE REGIONAL MUNICIPALITY OF NIAGARA
2201 ST. DAVID'S ROAD, THOROLD, ON, L2V-4T7

Long-Term Care Home/Foyer de soins de longue durée

DEER PARK VILLA
150 CENTRAL AVENUE, GRIMSBY, ON, L3M-4Z3

Name of Inspector(s)/Nom de l'inspecteur ou des inspecteurs

BERNADETTE SUSNIK (120)

Inspection Summary/Résumé de l'inspection



The purpose of this inspection was to conduct an Other inspection.

This inspection was conducted on the following date(s): October 2, 2013

A post-occupancy inspection was conducted following the completion of the newly built long-term care home.

During the course of the inspection, the inspector(s) spoke with the administrator and corporate building services manager.

During the course of the inspection, the inspector(s) toured all areas of the building, observed available furnishings, supplies and equipment, took illumination levels, water temperatures, tested elevator doors, tested magnetically locked doors and alarms and tested the resident-staff communication and response system.

The following Inspection Protocols were used during this inspection:
Safe and Secure Home

Findings of Non-Compliance were found during this inspection.

NON-COMPLIANCE / NON - RESPECT DES EXIGENCES	
Legend	Legendé
WN – Written Notification	WN – Avis écrit
VPC – Voluntary Plan of Correction	VPC – Plan de redressement volontaire
DR – Director Referral	DR – Aiguillage au directeur
CO – Compliance Order	CO – Ordre de conformité
WAO – Work and Activity Order	WAO – Ordres : travaux et activités



Ministry of Health and
Long-Term Care

Ministère de la Santé et des
Soins de longue durée

Inspection Report under
the Long-Term Care
Homes Act, 2007

Rapport d'inspection sous la
Loi de 2007 sur les foyers de
soins de longue durée

Non-compliance with requirements under the Long-Term Care Homes Act, 2007 (LTCHA) was found. (A requirement under the LTCHA includes the requirements contained in the items listed in the definition of "requirement under this Act" in subsection 2(1) of the LTCHA.)

The following constitutes written notification of non-compliance under paragraph 1 of section 152 of the LTCHA.

Le non-respect des exigences de la Loi de 2007 sur les foyers de soins de longue durée (LFSLD) a été constaté. (Une exigence de la loi comprend les exigences qui font partie des éléments énumérés dans la définition de « exigence prévue par la présente loi », au paragraphe 2(1) de la LFSLD.

Ce qui suit constitue un avis écrit de non-respect aux termes du paragraphe 1 de l'article 152 de la LFSLD.



WN #1: The Licensee has failed to comply with O.Reg 79/10, s. 18. Every licensee of a long-term care home shall ensure that the lighting requirements set out in the Table to this section are maintained. O. Reg. 79/10, s. 18.

TABLE

Homes to which the 2009 design manual applies

Location - Lux

Enclosed Stairways - Minimum levels of 322.92 lux continuous consistent lighting throughout

All corridors - Minimum levels of 322.92 lux continuous consistent lighting throughout

In all other areas of the home, including resident bedrooms and vestibules, washrooms, and tub and shower rooms. - Minimum levels of 322.92 lux

All other homes

Location - Lux

Stairways - Minimum levels of 322.92 lux continuous consistent lighting throughout

All corridors - Minimum levels of 215.28 lux continuous consistent lighting throughout

In all other areas of the home - Minimum levels of 215.28 lux

Each drug cabinet - Minimum levels of 1,076.39 lux

At the bed of each resident when the bed is at the reading position - Minimum levels of 376.73 lux

O. Reg. 79/10, s. 18, Table; O. Reg. 363/11, s. 4

Findings/Faits saillants :

The lighting requirements set out in the lighting table for the family rooms on both 1st and 2nd floors have not been maintained.

The family rooms each have 6 pot lights for general room lighting. When the illumination levels were measured with a light meter directly under the pot lights, the lux was 400-500. However, when the meter was moved away, toward the space between the pot lights, the lux dropped to 190 lux. The window coverings were open at the time of the test and it was sunny outdoors and some of the illumination would have been higher than what could be encountered at night time. The minimum requirement is 322.92 lux. [s.18]



Ministry of Health and
Long-Term Care

Ministère de la Santé et des
Soins de longue durée

Inspection Report under
the Long-Term Care
Homes Act, 2007

Rapport d'inspection sous la
Loi de 2007 sur les foyers de
soins de longue durée

Issued on this 7th day of October, 2013

Signature of Inspector(s)/Signature de l'inspecteur ou des inspecteurs

B. Susnik