

## Inspection Report Under the Fixing Long-Term Care Act, 2021

### Ministry of Long-Term Care

Long-Term Care Operations Division Long-Term Care Inspections Branch

### **London District**

130 Dufferin Avenue, 4th Floor London, ON, N6A 5R2 Telephone: (800) 663-3775

	<b>Original Public Report</b>
Report Issue Date: July 12, 2024	
Inspection Number: 2024-1225-0004	
Inspection Type:	
Complaint	
Licensee: Sharon Farms & Enterprises Limited	
Long Term Care Home and City: Kensington Village, London	
Lead Inspector	Inspector Digital Signature
Christie Birch (740898)	
Additional Inspector(s)	

# **INSPECTION SUMMARY**

The inspection occurred onsite on the following date(s): July 4, 8, 9, 2024 The inspection occurred offsite on the following date(s): July 5, 2024

The following intake(s) were inspected:

• Intake: #00119773 - Complaint intake related to air temperatures in the home.

The following Inspection Protocols were used during this inspection:

Safe and Secure Home Infection Prevention and Control



### Inspection Report Under the Fixing Long-Term Care Act, 2021

#### Ministry of Long-Term Care

Long-Term Care Operations Division Long-Term Care Inspections Branch

### **London District**

130 Dufferin Avenue, 4th Floor London, ON, N6A 5R2 Telephone: (800) 663-3775

# **INSPECTION RESULTS**

### WRITTEN NOTIFICATION: Air Temperature

NC #001 Written Notification pursuant to FLTCA, 2021, s. 154 (1) 1.

### Non-compliance with: O. Reg. 246/22, s. 24 (2) 2.

Air temperature

s. 24 (2) Every licensee of a long-term care home shall ensure that the temperature is measured and documented in writing, at a minimum in the following areas of the home:

2. One resident common area on every floor of the home, which may include a lounge, dining area or corridor.

The licensee failed to ensure that the temperature was measured and documented in writing in one resident common area on every floor of the home, which may include a lounge, dining area or corridor.

#### **Rationale and Summary**

During an inspection in the home related to air temperatures, it was noted in the temperature log that air temperatures were being taken on each shift by nursing staff, which included two resident rooms in different areas of the home and one common space in the home. These rooms were assigned by a rotating master monthly schedule.

The home consisted of five resident home areas on two floors.

The Director of Care (DOC) confirmed that the registered staff were not taking air temperatures of a common space on both floors of the home with each shift and should have been.



# Inspection Report Under the Fixing Long-Term Care Act, 2021

### Ministry of Long-Term Care

Long-Term Care Operations Division Long-Term Care Inspections Branch

### London District

130 Dufferin Avenue, 4th Floor London, ON, N6A 5R2 Telephone: (800) 663-3775

There was risk to the residents related to the possibility of the air temperature varying on different floors in the home.

**Sources:** Interview with the DOC and record review of the air temperature logs. [740898]