



**Ministry of Health and
Long-Term Care**

**Inspection Report under
the Long-Term Care
Homes Act, 2007**

**Ministère de la Santé et des
Soins de longue durée**

**Rapport d'inspection sous la
Loi de 2007 sur les foyers de
soins de longue durée**

**Health System Accountability and
Performance Division
Performance Improvement and
Compliance Branch**

**Division de la responsabilisation et de la
performance du système de santé
Direction de l'amélioration de la
performance et de la conformité**

Toronto Service Area Office
5700 Yonge Street, 5th Floor
TORONTO, ON, M2M-4K5
Telephone: (416) 325-9660
Facsimile: (416) 327-4486

Bureau régional de services de
Toronto
5700, rue Yonge, 5e étage
TORONTO, ON, M2M-4K5
Téléphone: (416) 325-9660
Télécopieur: (416) 327-4486

Public Copy/Copie du public

Report Date(s) / Date(s) du Rapport	Inspection No / No de l'inspection	Log # / Registre no	Type of Inspection / Genre d'inspection
Apr 25, 2014	2014_357101_0009	T-455-14	Critical Incident System

Licensee/Titulaire de permis

VIGOUR LIMITED PARTNERSHIP ON BEHALF OF VIGOUR
302 Town Centre Blvd, Suite #200, MARKHAM, ON, L3R-0E8

Long-Term Care Home/Foyer de soins de longue durée

LEISUREWORLD CAREGIVING CENTRE - CHELTENHAM
5935 BATHURST STREET, NORTH YORK, ON, M2R-1Y8

Name of Inspector(s)/Nom de l'inspecteur ou des inspecteurs

AMANDA WILLIAMS (101)

Inspection Summary/Résumé de l'inspection

The purpose of this inspection was to conduct a Critical Incident System inspection.

This inspection was conducted on the following date(s): April 8, 2014

During the course of the inspection, the inspector(s) spoke with the Administrator and Environmental Services Manager.

During the course of the inspection, the inspector(s) reviewed the home's emergency contingency plans policies and procedures, contracts and written records of tests completed.

The following Inspection Protocols were used during this inspection:
Safe and Secure Home



**Ministry of Health and
Long-Term Care**

**Inspection Report under
the Long-Term Care
Homes Act, 2007**

**Ministère de la Santé et des
Soins de longue durée**

**Rapport d'inspection sous la
Loi de 2007 sur les foyers de
soins de longue durée**

Findings of Non-Compliance were found during this inspection.

NON-COMPLIANCE / NON - RESPECT DES EXIGENCES

Legend

WN – Written Notification
VPC – Voluntary Plan of Correction
DR – Director Referral
CO – Compliance Order
WAO – Work and Activity Order

Legendé

WN – Avis écrit
VPC – Plan de redressement volontaire
DR – Aiguillage au directeur
CO – Ordre de conformité
WAO – Ordres : travaux et activités

Non-compliance with requirements under the Long-Term Care Homes Act, 2007 (LTCHA) was found. (A requirement under the LTCHA includes the requirements contained in the items listed in the definition of "requirement under this Act" in subsection 2(1) of the LTCHA.)

The following constitutes written notification of non-compliance under paragraph 1 of section 152 of the LTCHA.

Le non-respect des exigences de la Loi de 2007 sur les foyers de soins de longue durée (LFSLD) a été constaté. (Une exigence de la loi comprend les exigences qui font partie des éléments énumérés dans la définition de « exigence prévue par la présente loi », au paragraphe 2(1) de la LFSLD.

Ce qui suit constitue un avis écrit de non-respect aux termes du paragraphe 1 de l'article 152 de la LFSLD.



Ministry of Health and
Long-Term Care

Inspection Report under
the Long-Term Care
Homes Act, 2007

Ministère de la Santé et des
Soins de longue durée

Rapport d'inspection sous la
Loi de 2007 sur les foyers de
soins de longue durée

WN #1: The Licensee has failed to comply with O.Reg 79/10, s. 19. Generators Specifically failed to comply with the following:

s. 19. (4) The licensee of a home to which subsection (2) or (3) applies shall ensure, not later than six months after the day this section comes into force, that the home has guaranteed access to a generator that will be operational within three hours of a power outage and that can maintain everything required under clauses (1) (a), (b) and (c). O. Reg. 79/10, s. 19 (4).

Findings/Faits saillants :

1. The home does not have guaranteed access to a generator that will be operational within 3 hours of a power outage that can maintain the required essential services as demonstrated December 21, 2013 when the home lost power for ~13 hours without a generator that could maintain all the required essential services in the home. [s. 19. (4)]
2. The home's current contract with Agility Ready Suite - generator supply company does not identify the time frame in which a generator will be provided to the home. The contract states that "availability of services and equipment shall be on a first-come, first-serve basis and Agility makes no representation or warranty with respect to the availability of equipment at any particular time". [s. 19. (4)]
3. The home was unable to provide confirmation that the following essential services would be connected to an imported generator in cases of power loss: heat, lighting in corridors, connection of a fridge and freezer. It was noted that the other required essential services are connected to the home's in-house generator. [s. 19. (4)]

Additional Required Actions:

VPC - pursuant to the Long-Term Care Homes Act, 2007, S.O. 2007, c.8, s.152(2) the licensee is hereby requested to prepare a written plan of correction for achieving compliance to ensure residents are kept safe and secure during a loss of power until such time that a generator that maintains all essential services in the home is connected, to be implemented voluntarily.



**Ministry of Health and
Long-Term Care**

**Inspection Report under
the Long-Term Care
Homes Act, 2007**

**Ministère de la Santé et des
Soins de longue durée**

**Rapport d'inspection sous la
Loi de 2007 sur les foyers de
soins de longue durée**

Issued on this 25th day of April, 2014

Signature of Inspector(s)/Signature de l'inspecteur ou des inspecteurs

A handwritten signature in black ink, appearing to read "D. Willis".