



**Ministry of Health and  
Long-Term Care**

**Inspection Report under  
the Long-Term Care  
Homes Act, 2007**

**Ministère de la Santé et des  
Soins de longue durée**

**Rapport d'inspection  
prévu le Loi de 2007 les  
foyers de soins de longue**

**Health System Accountability and Performance  
Division**

**Performance Improvement and Compliance Branch**

**Division de la responsabilisation et de la  
performance du système de santé**

**Direction de l'amélioration de la performance et de la  
conformité**

Ottawa Service Area Office  
347 Preston St, 4th Floor  
OTTAWA, ON, K1S-3J4  
Telephone: (613) 569-5602  
Facsimile: (613) 569-9670

Bureau régional de services d'Ottawa  
347, rue Preston, 4iém étage  
OTTAWA, ON, K1S-3J4  
Téléphone: (613) 569-5602  
Télécopieur: (613) 569-9670

**Public Copy/Copie du public**

Date(s) of inspection/Date(s) de l'inspection	Inspection No/ No de l'inspection	Type of Inspection/Genre d'inspection
Jun 14, 20, 21, 2012	2012_054133_0026	Critical Incident

**Licensee/Titulaire de permis**

COUNTY OF RENFREW

9 INTERNATIONAL DRIVE, PEMBROKE, ON, K8A-6W5

**Long-Term Care Home/Foyer de soins de longue durée**

MIRAMICHI LODGE

725 Pembroke Street West, PEMBROKE, ON, K8A-8S6

**Name of Inspector(s)/Nom de l'inspecteur ou des inspecteurs**

JESSICA LAPENSEE (133)

**Inspection Summary/Résumé de l'inspection**

The purpose of this inspection was to conduct a Critical Incident inspection.

During the course of the inspection, the inspector(s) spoke with the Administrator, a Registered Practical Nurse, a Personal Support Worker and an ArjoHuntleigh Field Service Technician.

During the course of the inspection, the inspector(s) reviewed a Critical Incident report, observed the Maxi Sky 600 ceiling lift in a tub room, reviewed inspection records relating to lifting equipment in the home, reviewed sections of the ArjoHuntleigh "Maxi Sky 600, Maxi Sky 600 ECS Instructions for Use" document (001.14150.33.EN rev 7, December 2010)

The following Inspection Protocols were used during this inspection:

Accommodation Services - Maintenance

There are no findings of Non-Compliance as a result of this inspection.

**NON-COMPLIANCE / NON-RESPECT DES EXIGENCES**



**Ministry of Health and  
Long-Term Care**

**Inspection Report under  
the Long-Term Care  
Homes Act, 2007**

**Ministère de la Santé et des  
Soins de longue durée**

**Rapport d'inspection  
prévu le Loi de 2007 les  
foyers de soins de longue**

Legend	Legendé
WN – Written Notification VPC – Voluntary Plan of Correction DR – Director Referral CO – Compliance Order WAO – Work and Activity Order	WN – Avis écrit VPC – Plan de redressement volontaire DR – Aiguillage au directeur CO – Ordre de conformité WAO – Ordres : travaux et activités
Non-compliance with requirements under the Long-Term Care Homes Act, 2007 (LTCHA) was found. (A requirement under the LTCHA includes the requirements contained in the items listed in the definition of "requirement under this Act" in subsection 2(1) of the LTCHA.)	Le non-respect des exigences de la Loi de 2007 sur les foyers de soins de longue durée (LFSLD) a été constaté. (Une exigence de la loi comprend les exigences qui font partie des éléments énumérés dans la définition de « exigence prévue par la présente loi », au paragraphe 2(1) de la LFSLD.)
The following constitutes written notification of non-compliance under paragraph 1 of section 152 of the LTCHA.	Ce qui suit constitue un avis écrit de non-respect aux termes du paragraphe 1 de l'article 152 de la LFSLD.

Issued on this 21st day of June, 2012

**Signature of Inspector(s)/Signature de l'inspecteur ou des inspecteurs**

A handwritten signature in black ink that reads "Jessica Lopensée". The signature is fluid and cursive, with "Jessica" on top and "Lopensée" below it, slightly overlapping.