



**Ministry of Health and  
Long-Term Care**

**Inspection Report under  
the Long-Term Care  
Homes Act, 2007**

**Health System Accountability and  
Performance Division  
Performance Improvement and  
Compliance Branch**

**Division de la responsabilisation et de la  
performance du système de santé  
Direction de l'amélioration de la  
performance et de la conformité**

Ottawa Service Area Office  
347 Preston St 4th Floor  
OTTAWA ON L1K 0E1  
Telephone: (613) 569-5602  
Facsimile: (613) 569-9670

**Ministère de la Santé et des  
Soins de longue durée**

**Rapport d'inspection sous la  
Loi de 2007 sur les foyers de  
soins de longue durée**

Bureau régional de services d'Ottawa  
347 rue Preston 4iém étage  
OTTAWA ON L1K 0E1  
Téléphone: (613) 569-5602  
Télécopieur: (613) 569-9670

**Public Copy/Copie du public**

<b>Report Date(s) / Date(s) du apport</b>	<b>Inspection No / No de l'inspection</b>	<b>Log # / Registre no</b>	<b>Type of Inspection / Genre d'inspection</b>
Apr 7, 2015	2015_178102_0016	O-000654-14	Critical Incident System

**Licensee/Titulaire de permis**

EXTENDICARE (CANADA) INC.  
3000 STEELES AVENUE EAST SUITE 700 MARKHAM ON L3R 9W2

**Long-Term Care Home/Foyer de soins de longue durée**

EXTENDICARE KAWARTHA LAKES  
125 Colborne Street East LINDSAY ON K0L 2V0

**Name of Inspector(s)/Nom de l'inspecteur ou des inspecteurs**

WENDY BERRY (102)

**Inspection Summary/Résumé de l'inspection**



**Ministry of Health and  
Long-Term Care**

**Inspection Report under  
the Long-Term Care  
Homes Act, 2007**

**Ministère de la Santé et des  
Soins de longue durée**

**Rapport d'inspection sous la  
Loi de 2007 sur les foyers de  
soins de longue durée**

**The purpose of this inspection was to conduct a Critical Incident System inspection.**

**This inspection was conducted on the following date(s): March 04 and March 17, 2015.**

**The home was toured during both days of the inspection. Residents' Council meeting minutes and documentation related to the HVAC system were reviewed. Operation of the mechanical ventilation system was checked in resident home areas(RHA).**

**During the course of the inspection, the inspector(s) spoke with the Administrator, the Director of Care (Acting), the Maintenance/Environmental Manager, a number of staff, several residents and visitors.**

**The following Inspection Protocols were used during this inspection:  
Accommodation Services - Maintenance**

**During the course of this inspection, Non-Compliances were issued.**

**2 WN(s)  
1 VPC(s)  
0 CO(s)  
0 DR(s)  
0 WAO(s)**



**Ministry of Health and  
Long-Term Care**

**Inspection Report under  
the Long-Term Care  
Homes Act, 2007**

**Ministère de la Santé et des  
Soins de longue durée**

**Rapport d'inspection sous la  
Loi de 2007 sur les foyers de  
soins de longue durée**

**NON-COMPLIANCE / NON - RESPECT DES EXIGENCES**

**Legend**

WN – Written Notification  
VPC – Voluntary Plan of Correction  
DR – Director Referral  
CO – Compliance Order  
WAO – Work and Activity Order

**Legendé**

WN – Avis écrit  
VPC – Plan de redressement volontaire  
DR – Aiguillage au directeur  
CO – Ordre de conformité  
WAO – Ordres : travaux et activités

Non-compliance with requirements under the Long-Term Care Homes Act, 2007 (LTCHA) was found. (a requirement under the LTCHA includes the requirements contained in the items listed in the definition of "requirement under this Act" in subsection 2(1) of the LTCHA).

Le non-respect des exigences de la Loi de 2007 sur les foyers de soins de longue durée (LFSLD) a été constaté. (une exigence de la loi comprend les exigences qui font partie des éléments énumérés dans la définition de « exigence prévue par la présente loi », au paragraphe 2(1) de la LFSLD.

The following constitutes written notification of non-compliance under paragraph 1 of section 152 of the LTCHA.

Ce qui suit constitue un avis écrit de non-respect aux termes du paragraphe 1 de l'article 152 de la LFSLD.

**WN #1: The Licensee has failed to comply with O.Reg 79/10, s. 90. Maintenance services**

**Specifically failed to comply with the following:**

**s. 90. (3) The licensee shall ensure that the home's mechanical ventilation systems are functioning at all times except when the home is operating on power from an emergency generator. O. Reg. 79/10, s. 90 (3).**

**Findings/Faits saillants :**



**Ministry of Health and  
Long-Term Care**

**Inspection Report under  
the Long-Term Care  
Homes Act, 2007**

**Ministère de la Santé et des  
Soins de longue durée**

**Rapport d'inspection sous la  
Loi de 2007 sur les foyers de  
soins de longue durée**

1. The licensee has failed to ensure that the mechanical ventilation system is functioning at all times, except when the home is operating on power from an emergency generator. [s. 90. (3)]

2. During the inspection on March 04, 2015, the mechanical ventilation system's exhaust function was identified to be non functional (no suction) in all areas that were checked in each of the 2 resident home areas (RHA). The lack of function was brought to the attention of management staff in the home at the time of the inspection.

The exhaust system was confirmed to be functional in all areas that were checked during the 2nd day of the inspection on March 17, 2015. An HVAC contractor repaired the system on March 16, 2015. [s. 90. (3)]

***Additional Required Actions:***

***VPC - pursuant to the Long-Term Care Homes Act, 2007, S.O. 2007, c.8, s.152(2)  
the licensee is hereby requested to prepare a written plan of correction for  
achieving compliance by implementing procedures to ensure that the mechanical  
ventilation system is functioning at all times, to be implemented voluntarily.***

---

**WN #2: The Licensee has failed to comply with O.Reg 79/10, s. 21. Every licensee of a long-term care home shall ensure that the home is maintained at a minimum temperature of 22 degrees Celsius. O. Reg. 79/10, s. 21.**

**Findings/Faits saillants :**



**Ministry of Health and  
Long-Term Care**

**Inspection Report under  
the Long-Term Care  
Homes Act, 2007**

**Ministère de la Santé et des  
Soins de longue durée**

**Rapport d'inspection sous la  
Loi de 2007 sur les foyers de  
soins de longue durée**

1. The licensee has failed to ensure that all areas of the home are maintained at a minimum air temperature of 22 degrees Celsius (C).

During the inspection on March 04, 2015 the air temperature in the Balsam RHA activity room was identified to be 19.8 degrees C in the center of the room at approximately 10:50 am.

During the inspection on March 17, 2015 the air temperature in the Balsam RHA activity room was identified to be 17.2 degrees C in the center of the room at approximately 2:30 pm. [s. 21.]

---

**Issued on this 7th day of April, 2015**

**Signature of Inspector(s)/Signature de l'inspecteur ou des inspecteurs**

**Original report signed by the inspector.**