

Ministry of Health and Long-Term Care

Inspection Report under the Long-Term Care Homes Act, 2007

Ministére de la Santé et des Soins de longue durée

Rapport d'inspection prévue le Loi de 2007 les foyers de soins de longue

Health System Accountability and Performance Division Performance Improvement and Compliance Branch

Division de la responsabilisation et de la performance du système de santé Direction de l'amélioration de la performance et de la conformité

Hamilton Service Area Office 119 King Street West, 11th Floor HAMILTON, ON, L8P-4Y7 Telephone: (905) 546-8294 Facsimile: (905) 546-8255 Bureau régional de services de Hamilton 119, rue King Ouest, 11iém étage HAMILTON, ON, L8P-4Y7 Téléphone: (905) 546-8294 Télécopieur: (905) 546-8255

## Public Copy/Copie du public

Date(s) of inspection/Date(s) de l'inspection	Inspection No/ No de l'inspection	Type of Inspection/Genre d'inspection
Nov 7, 2011	2011_072120_0036	Critical Incident
Licensee/Titulaire de permis	Provident volga Provident Scott PRIP (g d. m. ) 4 4.	
IDLEWYLD MANOR  449 SANATORIUM ROAD, HAMILTO  Long-Term Care Home/Foyer de soi		
IDLEWYLD MANOR 449 SANATORIUM ROAD, HAMILTO	N, ON, L9C-2A7	
Name of Inspector(s)/Nom de l'insp	ecteur ou des inspecteurs	
BERNADETTE SUSNIK (120)		
ln ln	spection Summary/Résumé de l'inspe	ection

The purpose of this inspection was to conduct a Critical Incident inspection.

During the course of the inspection, the inspector(s) spoke with the Executive Director, Director of Resident Services, Environmental Services Manager and health care workers regarding the submission of critical incident #2931-000027-11 (H-002043-11) relating to maintenance services.

During the course of the inspection, the inspector(s) toured several home areas, reviewed maintenance policies and procedures, service records for the heating/ventilation system, mechanical lift equipment inspection check lists and observed the operation of a disinfectant washer.

The following Inspection Protocols were used during this inspection: Accommodation Services - Maintenance

Findings of Non-Compliance were found during this inspection.

## NON-COMPLIANCE / NON-RESPECT DES EXIGENCES



Ministry of Health and Long-Term Care

Inspection Report under the Long-Term Care Homes Act, 2007 Ministère de la Santé et des Soins de longue durée

Rapport d'inspection prévue le Loi de 2007 les foyers de soins de longue

Legend	Legendé
process and the same of the sa	WN – Avis écrit VPC – Plan de redressement volontaire DR – Algulllage au directeur CO – Ordre de conformité WAO – Ordres : travaux et activités
	Le non-respect des exigences de la Loi de 2007 sur les foyers de soins de longue durée (LFSLD) a été constaté. (Une exigence de la loi comprend les exigences qui font partie des éléments énumérés dans la définition de « exigence prévue par la présente loi », au paragraphe 2(1) de la LFSLD.
The following constitutes written notification of non-compliance under paragraph 1 of section 152 of the LTCHA.	Ce qui sult constitue un avis écrit de non-respect aux termes du paragraphe 1 de l'article 152 de la LFSLD.

WN #1: The Licensee has failed to comply with O.Reg 79/10, s. 90. Maintenance services Specifically failed to comply with the following subsections:

- s. 90. (1) As part of the organized program of maintenance services under clause 15 (1) (c) of the Act, every licensee of a long-term care home shall ensure that,
- (a) maintenance services in the home are available seven days per week to ensure that the building, including both interior and exterior areas, and its operational systems are maintained in good repair; and
- (b) there are schedules and procedures in place for routine, preventive and remedial maintenance. O. Reg. 79/10, s. 90 (1).
- s. 90. (2) The licensee shall ensure that procedures are developed and implemented to ensure that,
- (a) electrical and non-electrical equipment, including mechanical lifts, are kept in good repair, and maintained and cleaned at a level that meets manufacturer specifications, at a minimum;
- (b) all equipment, devices, assistive aids and positioning aids in the home are kept in good repair, excluding the residents' personal aids or equipment;
- (c) heating, ventilation and air conditioning systems are cleaned and in good state of repair and inspected at least every six months by a certified individual, and that documentation is kept of the inspection;
- (d) all plumbing fixtures, toilets, sinks, grab bars and washroom fixtures and accessories are maintained and kept free of corrosion and cracks;
- (e) gas or electric fireplaces and heat generating equipment other than the heating system referred to in clause (c) are inspected by a qualified individual at least annually, and that documentation is kept of the inspection:
- (f) hot water boilers and hot water holding tanks are serviced at least annually, and that documentation is kept of the service;
- (g) the temperature of the water serving all bathtubs, showers, and hand basins used by residents does not exceed 49 degrees Celsius, and is controlled by a device, inaccessible to residents, that regulates the temperature;
- (h) immediate action is taken to reduce the water temperature in the event that it exceeds 49 degrees Celsius;
- (i) the temperature of the hot water serving all bathtubs and showers used by residents is maintained at a temperature of at least 40 degrees Celsius;
- (j) if the home is using a computerized system to monitor the water temperature, the system is checked daily to ensure that it is in good working order; and
- (k) if the home is not using a computerized system to monitor the water temperature, the water temperature is monitored once per shift in random locations where residents have access to hot water. O. Reg. 79/10, s. 90 (2).

Findings/Faits saillants:



Ministry of Health and Long-Term Care

Inspection Report under the Long-Term Care Homes Act, 2007 Ministère de la Santé et des Soins de longue durée

Rapport d'inspection prévue le Loi de 2007 les foyers de soins de longue

1. [O.Reg.79/10,s.90(1)(b)] The Environmental Services Manager confirmed that policies, procedures and schedules have not been developed for the care and maintenance of the Tornado disinfecting washers.

2. [O.Reg.79/10,s.90(2)(a)] The Tornado disinfecting machine located in Rose Garden home area soiled utility room is not maintained according to the manufacturer's minimum specifications. The unit was monitored throughout the wash, rinse and disinfection stages with the Environmental Services Manager. The unit did not achieve a minimum water temperature of 40C during the wash cycle as per the manufacturer's specifications. The digital temperature gauge attached to the machine remained at 25C.

Issued on this 21st day of November, 2011

Signature of Inspector(s)/Signature de l'inspecteur ou des inspecteurs

8. Juant