



# Inspection Report under the *Long-Term Care Homes Act, 2007*

# Rapport d'inspection prevue le *Loi de 2007 les foyers de soins de longue durée*

**Ministry of Health and Long-Term Care**  
Health System Accountability and Performance Division  
Performance Improvement and Compliance Branch

## Ministère de la Santé et des Soins de longue durée

Division de la responsabilisation et de la performance du  
système de santé  
Direction de l'amélioration de la performance et de la  
conformité

Hamilton Service Area Office  
119 King Street West, 11<sup>th</sup> Floor  
Hamilton, ON L8P 4Y7

Telephone: 905-546-8294  
Facsimile: 905-546-8255

Bureau régional de services de Hamilton  
119, rue King Quest, 11<sup>th</sup> étage  
Hamilton, ON L8P 4Y7

Téléphone: 905-546-8294  
Télécopieur: 905-546-8255

<input type="checkbox"/> Licensee Copy/Copie du Titulaire <input checked="" type="checkbox"/> Public Copy/Copie Public		
Date of inspection/Date de l'inspection	Inspection No/ d'inspection	Type of Inspection/Genre d'inspection
03 March 2011	2011_127_8564_02Mar161321	Critical Incident # H-00475
Licensee/Titulaire St. Joseph's Health System, 574 Northcliffe Avenue, Dundas ON L9H 7L9		
Long-Term Care Home/Foyer de soins de longue durée St. Joseph's Health Centre – Guelph, 100 Westmount Road, Guelph ON		
Name of Inspector(s)/Nom de l'inspecteur(s) Richard Hayden, Long Term Care Homes Inspector – Environmental Health #127		
Inspection Summary / Sommaire d'inspection		
<p>The purpose of this visit was to conduct a critical incident inspection.</p> <p>During the course of the inspection, the inspector spoke with maintenance staff; manager, environmental services; coordinator, quality, risk and patient safety; vice president clinical services; and assistant director of care.</p> <p>During the course of the inspection, the inspector confirmed the functionality of the elevators in the north wing.</p> <p>The following Inspection Protocols were used during this inspection:</p> <ul style="list-style-type: none"><li>• Safe and Secure Home</li></ul> <p>No findings of non-compliance were found during this inspection.</p>		

Signature of Licensee or Representative of Licensee Signature du Titulaire du représentant désigné	Signature of Health System Accountability and Performance Division représentative/Signature du (de la) représentant(e) de la Division de la responsabilisation et de la performance du système de santé.  
Title: Date:	Date of Report (if different from date(s) of inspection). 07 March 2011