



**Ministry of Health and  
Long-Term Care**  
**Inspection Report under  
the Long-Term Care  
Homes Act, 2007**

**Ministère de la Santé et des  
Soins de longue durée**  
**Rapport d'inspection  
prévu la Loi de 2007 les  
foyers de soins de longue**

**Health System Accountability and Performance**

**Division**  
**Performance Improvement and Compliance Branch**  
**Division de la responsabilisation et de la  
performance du système de santé**  
**Direction de l'amélioration de la performance et de la  
conformité**

Hamilton Service Area Office  
119 King Street West, 11th Floor  
HAMILTON, ON, L8P-4Y7  
Telephone: (905) 546-8294  
Facsimile: (905) 546-8255

Bureau régional de services de Hamilton  
119, rue King Ouest, 11<sup>me</sup> étage  
HAMILTON, ON, L8P-4Y7  
Téléphone: (905) 546-8294  
Télécopieur: (905) 546-8255

**Public Copy/Copie du public**

Date(s) of inspection/Date(s) de l'inspection	Inspection No/ No de l'inspection	Type of Inspection/Genre d'inspection
Dec 1, 2011	2011_072120_0044	Complaint

**Licensee/Titulaire de permis**

REVERA LONG TERM CARE INC.  
55 STANDISH COURT, 8TH FLOOR, MISSISSAUGA, ON, L5R-4B2

**Long-Term Care Home/Foyer de soins de longue durée**

BRIERWOOD GARDENS  
425 PARK ROAD NORTH, BRANTFORD, ON, N3R-7G5

**Name of Inspector(s)/Nom de l'inspecteur ou des inspecteurs**

BERNADETTE SUSNIK (120)

**Inspection Summary/Résumé de l'inspection**

The purpose of this inspection was to conduct a Complaint inspection.

During the course of the inspection, the inspector(s) spoke with executive director, director of care, health care aides, registered staff and residents regarding the asbestos abatement and sprinkler system installation projects that occurred in August and September 2011.

During the course of the inspection, the inspector(s) toured the home, reviewed resident care documents, material safety data sheets for materials used during the sprinkler installation process, indoor air quality test results and asbestos abatement removal plans and protocols.

The following Inspection Protocols were used during this inspection:

Safe and Secure Home

There are no findings of Non-Compliance as a result of this inspection.

**NON-COMPLIANCE / NON-RESPECT DES EXIGENCES**



**Ministry of Health and  
Long-Term Care**  
**Inspection Report under  
the Long-Term Care  
Homes Act, 2007**

**Ministère de la Santé et des  
Soins de longue durée**  
**Rapport d'inspection  
prévu le Loi de 2007 les  
foyers de soins de longue**

Legend	Legendé
WN – Written Notification VPC – Voluntary Plan of Correction DR – Director Referral CO – Compliance Order WAO – Work and Activity Order	WN – Avis écrit VPC – Plan de redressement volontaire DR – Aiguillage au directeur CO – Ordre de conformité WAO – Ordres : travaux et activités
Non-compliance with requirements under the Long-Term Care Homes Act, 2007 (LTCHA) was found. (A requirement under the LTCHA includes the requirements contained in the items listed in the definition of "requirement under this Act" in subsection 2(1) of the LTCHA.)  The following constitutes written notification of non-compliance under paragraph 1 of section 152 of the LTCHA.	Le non-respect des exigences de la Loi de 2007 sur les foyers de soins de longue durée (LFSLD) a été constaté. (Une exigence de la loi comprend les exigences qui font partie des éléments énumérés dans la définition de « exigence prévue par la présente loi », au paragraphe 2(1) de la LFSLD.  Ce qui suit constitue un avis écrit de non-respect aux termes du paragraphe 1 de l'article 152 de la LFSLD.

Issued on this 9th day of December, 2011

**Signature of Inspector(s)/Signature de l'inspecteur ou des inspecteurs**